






Energy Recovery, Inc.
 1908 Doolittle Dr.
 San Leandro, CA
 94577, USA
 Phone: 510-483-7370
 Fax: 510-483-7371

**PERFORMANCE CURVES
 PX-120 PRESSURE
 EXCHANGER**

REV	BY	CKD	REVISION	DATE
000	RBC	RLS	Issued for Distribution	6/24/04
001	RLS	RBC	Corrected Lube Curve	10/15/04

Doc. No.	80028-01
Sheet No.	1 of 1



NOTE: SEE ERI DOCUMENT NUMBER 80008-01 FOR DEFINITIONS AND TEST CONDITIONS