






Energy Recovery, Inc.
 1908 Doolittle Dr.
 San Leandro, CA
 94577, USA
 Phone: 510-483-7370
 Fax: 510-483-7371

**ENERGY RECOVERY, INC.
 PRESSURE EXCHANGER
 PX-180**

Doc. No. 80013-01
 Sheet No. 1 of 1

REV	BY	CKD	REVISION	DATE
01	RLS	RBC	Revised Metric Scale	7/29/04
02	RLS	RBC	updated data	6/29/05
03	JMP	RLS	Updated data	1/16/06
04	RLS	IBC	Increased flow range	4/11/08
05	IBC	RLS	Recalibrated lube & HPDP	8/8/08



NOTE: SEE ERI DOCUMENT NUMBER 80008-01 FOR DEFINITIONS AND TEST CONDITIONS