






Energy Recovery, Inc.
 1908 Doolittle Dr.
 San Leandro, CA
 94577, USA
 Phone: 510-483-7370
 Fax: 510-483-7371

**PERFORMANCE CURVES
 PX-140S PRESSURE
 EXCHANGER**

REV	BY	CKD	REVISION	DATE
000	RLS	RBC	Issued for Distribution	8/5/04
001	RBC	RLS	Revised Mixing Curve	10/3/05

Doc. No.	80039-01
Sheet No.	1 of 1



NOTE: SEE ERI DOCUMENT NUMBER 80008-01 FOR DEFINITIONS AND TEST CONDITIONS