



1908 Doolittle Dr.
San Leandro, CA
94577, USA
Phone: 510-483-7370
Fax: 510-483-7371

ENERGY RECOVERY, INC.
HP 2402
PX BOOSTER PUMP

REV	BY	CKD	REVISION	DATE
000	RLS	JPM	Issued for Distribution	11/23/04
001	RLS	RBC	revised efficiency curve	7/12/05
002	JMP	RLS	Updated data	12/25/05
003	JMP	RLS	Revised efficiency and DP curves	04/10/06

DESCRIPTION

PUMP CURVES
HIGH-PRESSURE BOOSTER PUMP

SHEET
1 of 1

DOCUMENT NUMBER
80044-05

MANUFACTURER
ERI

