



1908 Doolittle Dr.
 San Leandro, CA
 94577, USA
 Phone: 510-483-7370
 Fax: 510-483-7371

ENERGY RECOVERY, INC.
 HP 8504
 PX BOOSTER PUMP

REV	BY	CKD	REVISION	DATE
000	RLS	JPM	Issued for Distribution	11/23/04
001	RLS	RBC	Revised efficiency curve	7/12/05
002	JMP	RLS	Updated data	4/10/06

DESCRIPTION

PUMP CURVES
 HIGH-PRESSURE BOOSTER PUMP

SHEET
 1 of 1

DOCUMENT NUMBER
 80044-02

MANUFACTURER
 ERI

