






Energy Recovery, Inc.  
 1908 Doolittle Dr.  
 San Leandro, CA  
 94577, USA  
 Phone: 510-483-7370  
 Fax: 510-483-7371

**PERFORMANCE CURVES  
 PX-90S PRESSURE  
 EXCHANGER**

Doc. No. 80034-01  
 Sheet No. 1 of 1

REV	BY	CKD	REVISION	DATE
000	RLS	JPM	Issued for Distribution	7/7/04



NOTE: SEE ERI DOCUMENT NUMBER 80008-01 FOR DEFINITIONS AND TEST CONDITIONS